

Young, Paul

From: Collinson, Gillian
Sent: 03 March 2022 15:25
To: Licensing ABC
Subject: FW: Review Application - Electric Soup

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Paul

Please could you include the email below as a representation to the review application and prepare a hearing pack for Env Health.

Thanks
Gill

From: Copeland, David <david.copeland@alldale.gov.uk>
Sent: 02 March 2022 14:43
To: Fletcher, Deborah <deborah.fletcher@alldale.gov.uk>; Licensing ABC <Licensing@Alldale.gov.uk>
Subject: Re: Review Application - Electric Soup

Hi, on review of the noise report of November 2021 it referred to Electric Soup along with the other business in that block. Music noise reports were received previously for Electric Soup in June 2019 and November 2018. When regulated entertainment is being undertaken it is imperative that all conditions with regards to noise control are adhered to at all times.

It is recommended that the conditions are reviewed to have the requirement for a noise management plan, with the requirement for a noise check be written as consecutively numbered conditions.

Young, Paul

From: Collinson, Gillian
Sent: 03 March 2022 15:51
To: Licensing ABC
Subject: FW: Electric Soup - Health and safety

Follow Up Flag: Follow up
Flag Status: Flagged

Please could the email below be included as part of the Environmental Health representation and included in the hearing notice pack?

Thanks
Gill

From: Horton, Rachel <rachel.horton@allderdale.gov.uk>
Sent: 03 March 2022 15:44
To: Tranter, Sian <sian.tranter@allderdale.gov.uk>; Collinson, Gillian <gillian.collinson@allderdale.gov.uk>
Subject: Electric Soup - Health and safety

A visit was made to Electric Soup and Canned Heat on the 5th November 2021 by myself and Ms Joy Hadden Environmental Health Officer. The following points were noted and required action

- Secure all gas cylinders
- Highlight all changes in level so they can be clearly seen.
- Ensure the cover plate on the fused spur in the ladies toilet in Canned heat is secured
- Replace or cover the area on the main access staircase where the spindles are missing
- Replace the handrail adjacent to the elevated seating in Electric Soup.
- Risk assess and control the risk of falling over the old balcony. Put in place a plan to reinforce the glass panels or reinstate the floor.
- Investigate the cause of the damp in the old VIP room , make repairs and remove all loosed flaking paint
- Ensure all PAT and electrical installation checks are up to date.
- Carry out risk assessments for both businesses which include manual handling and COSHH.

Food Safety

- Seal all bare wood
- Cover open ports in the drinks machine (electric soup) to minimize the risk of contamination

Recommendations.

- Improve the house lighting in both venues
- Discuss with the other tenants of the building and the landlord the maintenance of communal areas such as the main stairway and fire exits to ensure risks are managed.

A follow up visit was carried out on the 25th November 2021 at which time the following matters were identified as outstanding or requiring action.

- Canned Heat
 - Replace metal strip by bar
 - Ensure multi-adapters are adequately supported
 - Seal all areas of bare wood
 - Recommendation to improve lighting at the entrance to the male WC to reduce tripping hazard.
- Electric Soup
 - Complete repairs to banisters
 - Repair reattach flooring on dance floor
 - Repair areas of damp or remove food equipment in old VIP area
 - Complete risk assessments.